# Er. Shashi Chandra Upadhyay

M. Tech (Structural Engineering), Licensed Structural Engineer (S.D.M.C) D-76, Chattarpur Enclave, New Delhi- 110074, Mob: 7011046431, 8826516054 E-mail:structurendesign@gmail.com, websit: www.sndcpl.com

Date: 18 06 22

### STRUCTURAL STABILITY CERTIFICATE

This is to certify that the structural part of Block-B, Additional Class Rooms (Ground Floor, 1st Floor, 2nd Floor, total covered area of all floors 15789.00 Sft ) in Gole Building (Sant Nagpal Public School) in Shree Adya Katyayani Shakti Peeth Mandir Trust Premises at Chhattarpur, New Delhi-110074 has been executed at site as per the design made by us on the basis of structural Calculations that are considered safe in accordance with the permissible stresses and slenderness ratio as laid down in accepted and up to date manual / regulations of Bureau of Indian standards applicable.

> With Thanks S.D.M.C. LICENSE No.

Shashi Chandra Upadhyay Structural Engineer SE - 150 (SDMC)

#### St. S.C. UPADHYAY

Chartered Civil Engineer
Structural Consultant



D-76, Chhattarpur Enclave, New Delhi-110 074

> Mob.: 9213394132 8826516054

Ref. No.

	12	to														
D	a	IC			•				٠			•				

Date: 27-12-2014

#### Certificate of Structural Stability (To whom it may concern)

Site: Gole Building (Sant Nagpal Public School) in Shri Adya Katyayani Shaktipeeth Mandir Trust Premises at Chhattarpur, New Delhi – 110074

BLOCK- 'A'

The Structural system including foundation, columns, beams & slab for Basement, Ground floor, 1<sup>st</sup> floor & II<sup>nd</sup> Floor (Total Area 24763 Sft.) of the building design has been checked on the basis of structural calculations and is considered safe in accordance with permissible stress and slenderness ration of steel and concrete.

it is certified that the building is safe and complete to take / carry the required load.

this is as per the request of Secretary, in Shri Adya Katyayani Shaktipeeth Mandir Trust Chartarpur.

Shashi Chandra Upadhyay

Structural Engineer SE – 150 (SDMC) Er. S.C. Upadhyay
Charted Civil Engineer, Structural Consultant
D-76, Chhattarpur Enclave, New Delhi -110074.
Mob.8826516054, 7011046431.

Date 09/10/17

## STRUCTURAL STABILITY CERTIFICATE TO WHOM IT MAY CONCERN

Site: Additional Class Rooms ( Ground Floor, 1<sup>ST</sup> Floor ,2<sup>ND</sup> Floor) in Gole Building (Sant Nagpal Public School) in Shree Adya Katyayani Shakti Peeth Mandir Trust Permises at Chhattarpur, New Delhi-110074.

BLOCK-C

This is to certify that the structural part of Additional Class Rooms ( Ground Floor, 1<sup>ST</sup> Floor, 2<sup>ND</sup> Floor total covered area of all floor 15168 Sft) in Gole Building (Sant Nagpal Public School) in Shree Adya Katyayani Shakti Peeth Mandir Trust Permises at Chhattarpur, New Delhi-110074.has been executed at site as per the design made by us on the basis of structural Calculations that are considered safe in accordance with the permissible stresses and slenderness ratio as laid down in accepted and up to date manual/regulations of Bureau of Indian standards applicable.

Shashi Chandra Upadhyay Structural Engineer SE – 150 (SDMC)

